Parts Change Information

Subject: Modification of Motor Control PCB 2 **Issue No.: 19507**

New Part #: 019-51040-203 New Description: Motor Control PCB 2 Old Part #: 019-51013-605 Old Description: Motor Control PCB 2	Reason For Change [ ] Cost Effective [ ] Eliminate Claims [X] Easier Operation [ ] Other	Manuf. Cut-in Serial # See Below	Applies to: GR SERIES
[ ] New	[x] Modified	[ ] Obsoleted	[ ] Other

SUMMARY:

The program for elevating the paper feed tray has been modified to improve the paper feed operation.

The Paper Feed Tray moves up more smoothly by reducing the interval of movement from 5 to 6 sheets to a new interval of 2 to 3 sheets between Elevator movement.

NEWLY REGISTERED PART:

1. 019-51040-203 Motor Control PCB 2

REPLACED PART:

1. 019-51013-605 Motor Control PCB 2

Serial Number Incorporation:

GR1700-UL	88462481
GR1750-UL	88481866
GR2700-UL	89380024
GR2710-UL	89451823
GR2750-UL	89502375
GR3710-UL	99440123
GR3750-UL	99460206
GR3770-UL	99471431